



Preliminary Drain Tile Investigation

Pallme Farm Solar (the Project)

ILSolar08LLC (the Applicant)

No drain tile is known to exist on the property, according to the Landowner and tenant farmer. No evidence of drain tile (either installation trenches or drainage patters) are visible on the available historical aerial imagery (Google Earth and Kane County GIS Aerial Imagery).

Prior to construction of the Project, applicant will hire an experienced drain tile installation and investigation company to perform an on-site drain tile investigation, in accordance with Kane County requirements.